



RECALL

- Recall Date:** February 18th 2008
- Potential units affected:** 800 (as of September 2007)
- Part Number:** VLSITINF 32120
- Description:** Quick Connect LP Inflate Hose 29"
- Summary:** Certain Dry suits that are equipped with inflation valves will also include the low pressure inflator hose. There is a possibility that the low pressure hose quick connect will snap off of the hose. Shipment of hoses in question began on Sept. 1st, 2007.
- Consequence:** As a result of the quick connect snapping off, it will drain the scuba tank.
- Remedy:** Dealers will replace the Quick Connect LP Inflate Hose 29" (VLSITINF 32120) with our previous style STD Low Pressure Inflate Hose (29") (VLSITINF32500).
White's Customer Service:
1-866-652-8556.
- Duration:** This recall is to start immediately and is expected to last until all hoses are replaced.

